

Invoice

	Date	
	Thursday, December	15, 2022
	Invoice No.	80994
30	Ford	Thunderbird

Description	Parts/			Mech	Fa	-h			
Description	Materials	_	Body	_ F	aint	Trim	Mecn	ra	ID
A Control of the Cont		+					3,00		
Vehicle inspection & test drive							2.00		
Source repair parts Remove & replace tires & tubes	2080.0	0					3.00		_
Balance tires							2.00		_
Alignment							3.00		_
Remove & replace left front caliper brake hose washer Bleed brakes	19.5	0					1.50		_
Remove & replace front sway bar links	39.0	0					1.00		
Remove & replace inner & outer tie rods & sleeves	340.6	0					8.00	-	_
Remove & replace power steering pump & high pressure hose	305.5	0		-			4.00		
Remove & replace valve cover gaskets & intake manifold gasket	71.5	0					6.00		
Remove & replace left motor mount & motor mount shield	65.0	0					1.50		
Remove & replace driveshaft universal joints (2) Balance driveshaft	65.0	10					3.50		
	60.0						4.00		
Remove & re[place rear differential gasket Remove & replace rear leaf spring & shackle bushings	117.0						4.00		
	247.0	_			====		1.00		
Remove & replace rear shocks	585.0						8.00		
Check radio & radio wiring Install new bluetooth radio	303.0	+	-	1			4.50		
Check dash lights inop Tighten connector pins & re-test	585.0			_			8.00		
Check wipers inop Electric wiper conversion				_			4.25		
Remove & replace headlight switch & high beam headlamps	312.0			_			8.00		
Under hood wiring check & repair	162.5	_				16.50	0.00		_
Check & repair / adjust rear quarter window filment	104.0			-		10.50	4.00		_
Check & repair stiff brake pedal	32.5	_		-			2.50		_
Remove & replace fuel pump fuel line Remove & replace fuel filter	65.0	_		_			1.00	_	_
Re- plumb windshield washer pump hoses	45.5	_		_			1.00	_	_
Remove & replace radiator cap	19.5	_		-			400	-	_
Check & repair intermittent brake lights	39.0	00					4.00		_
Remove & replace battery cables & ignition switch	156.0	00					4.50		_
Elecctronic fuel injection upgrade	4680.0	00					51.5D	_	
Install O2 port Test & tune fuel injection system	52.0	00					23.25		_
Remove & replace spark plugs & spark plug wires	169.0	00	==				3.75		
Remove & replace distributor cap & distributor rotor	52.0	ю					1.00		
Remove & replace oil pan gasket	39.0	00					4.50		_
Remove & replace thermostat & gasket Flush & re-fill coolant	104.0	00					2.00		
Change engine oil & filter Lube chassis	71.5	_					0.75		
Clean & polish valve covers							3.00		
		#17	7.00						
Rub out & polish body Misc. nuts, bolts, wire, wire connectors & fluids	91,0								
	78.0	_							
Fuel	76.	-							
		-							
Total Labor Hours			7.00			16.50	186.00		
Labor Rate per Haur		\$	85.00	\$	85.00	\$ 85.00	\$ 95.00	\$ 6	85.0
To als	\$ 10,852.6		595.00	_	7.0	\$ 1,402.50	\$ 17,670.00	\$	
10-016	\$ 10,002.0	Ť							
	\$ -								
	\$ -	-							
	1.35								

20 T 10 20 40 K CO	Parts/			Labor Houn	8	
Description	Materials	Body	Paint	Trim	Mech	Fab
Remittance Address: 24331 Brest Road Taylor, MI 48180 Ph: (734) 947-7002 Fax: (734) 947-2551	Materials subtotal				\$	10,852.60
Email: vendor@mcshotrod.com	Labor subtotal				\$	19,667.50
Motor Vehicle Registration No: F165288	Shop supplies				\$	30,00
All Repairs Properly Performed P.A. 300	Outsourced work				\$	
	Shipping fees				\$	700.00
	Transport vehicle				\$	
u .	SUBTOTAL				\$	31,250.10
Mechanic's Name & MI Certification No.	MI sales tax @ 6%				\$	694.95
Scott Dronsella #M202111	TOTAL JOB COS				\$	31,945.05
Rick Carpenter #M273182	Payments/Credits				S	*
Rick Carpenter #m2/3102	25/				\$	
	BALANCE DUE				\$	31,945.05



Invoice

Date
Tuesday, November 26, 2024

Invoice No. 80994-01

1960 Ford Thunderbird 0

Labor Rates: Body \$95.00 Paint \$95.00 Trim \$95.00 Mech \$	Parts/ Labor Hours			n same y		
Description	Materials	Body	Paint	Trim	Mech	Fab
					6.00	
Resealed transmission shifter linkage and pan gasket	13.00				6.00	_
Repair valve cover gasket leak No charge					6.00	
Repair intake manifold gasket leak	52.00		1		0.50	
Repair master cylinder cap seal leak	10.40		-		1.50	
Repair speedometer cable leak	13.00				1.50	
Repair road draft tube seal leak	19.50				1.50	
Repair fuel leak at fuel filter. No charge					0.00	
Repair rh side exhaust hanger	26.00				2.00	
Remove & replace power steering control valve & hoses	617.50				4.00	
Check & re-fill power steering fluid	13.00					
Check / adjust alignment					2.00	
Change engine oil & filter	65.00				0.50	
Replaced valve cover gaskets	19.18				1.50	
Replaced intake manifold gaskets					8.00	
Removed and replaced steering column/gear shift	383.50				8.00	
Remove and replaced steering continues and replace turn signal switch	140.40				3.00	
Remove and replace turn digital officer						
		1				
Total Labor Hours		0.00	0.00	0.5.00	44.50	C 050
Labor Rate per Hour		\$ 95.00		\$ 95.00	\$ 95.00	\$ 95.0
Totals	\$ 1,372.48	\$ -	\$ -	\$ -	\$ 4,227.50	\$ -
	\$ -					
	\$ -					
	\$ -					
Total Outsourced Work		U.S. Ingeles		No.	1.530 100	DAY HE WIT
Remittance Address: 24331 Brest Road Taylor, MI 48180	AVEL NO.					
Ph: (734) 947-7002 Fax: (734) 947-2551	Materials sul	ototal			\$	1,372.4
Ph: (734) 947-7002 Fax: (734) 947-2551	16.00	\$	4,227.5			
	cle Registration No: F165288 Shop supplies S					50.0
Motor Vehicle Registration No: F165288						-
All Repairs Properly Performed P.A. 300						30.0
	Shipping fee			STEEDINGS SHAVE		50.0
	Transport ve	hicle			\$	5,679.9
X	-					
Mechanic's Name & MI Certification No.	MI sales tax				\$	82.3
Scott Dronsella #M202111	TOTAL JOB			140 - 19	\$	5,762.3
Rick Carpenter #M273182	Payments/Ci	redits Receive	ed	- 1	\$	(7)
					\$	
	BALANCE D	HE			\$	5,762.3

Extrusion Punch & Tool Bill To:

INVOICE

DATE: INVOICE # January 7, 2022

I-16375

DESCRIPTION	AMOUNT
1960 Ford Thunderbird Repair Invoice	\$ -
Replace and paint new water pump (not rebuilt), thermostat gasket and hose nipple	775.00
Replaced power steering control valve	775.00
Remove tail light housing and disassemble the tail light assembly. Rebuild the electrical	140.00
sockets and changed bad light bulbs	
Ignition off draw was 4-6 amps. It has a single wire self-excited alternator with the	500.00
regulator removed. Found a draw to a previously added relay under the dash and another	
strong draw to a relay on the firewall. Added a relay near the battery to kill power until excited	
by the ignition switch. Amperage draw is now about 25mA	
Rewire the power feed to the power window relay so that the solenoid is not activated all	160.00
of the time. Added a relay for ignition off control.	
TOTAL	\$ 2,350.00

Extrusion Punch & Tool Bill To:

INVOICE

DATE: INVOICE # January 26, 2022 I-16383

DESCRIPTION	AMOUNT
1960 Ford Thunderbird Convertible repairs	
Upper and lower ball joints are original and bad. Replace 2 upper and 2 lower ball joints	500.00
Parts \$150.00, Labor \$350.00	
Upper control arm bushings (2/side) are bad. Rubber extremely dried up and cracked and	700.00
bushings siezed on shaft and spinning in the control arm. Burn out and press out the old	
ones. Press in new ones with properly supported A-frame.	
Parts \$100.00, Labor \$600.00	
Alignment. Parts \$200.00, Labor \$75.00	275.00
Front brake slider pins were hitting rims. These are converted to the GM floating caliper	50.00
brakes someone didn't measure correctly. Did some cutting and grinding on the pins to	
provide clearance to rims. Labor \$50.00	
Oil pan drain plug leaking. Dump the oil, replace the drain plug seal and add new oil.	100.00
Parts \$60.00, Labor \$40.00	
Added gas	50.00
	ERSES IN CONCUED DO NOT SOME
TOTAL	\$ 1,675.00



EDL Services LLC

Antique / Classic Car Repair 1135 Badder Ave. Troy, MI 48083 (248) 797-8781

Make of Car

1960 Ford Thunderbird

Invoice #3431

		Cost of	THISON	
	<u>, </u>	Parts	Quantity	AMOUNT
9/12/2023	Plug Harness for ECU System	161.84	1	161.84
	Holley Terminator X 3.5 Touch	492.83	1	492.83
Close Date	Vacuum Control Line	69.09	1	69.09
1/11/2024	Accelerator Pedal & Rod	79.17	1	79.17
	6AN Fuel Line Kit	100.49	1	100.49
	6AN Line Fittings	41.31	1	41.31
	Air Fuel Sensor	226.88	1	226.88
	Gaskets (pair)	4.14	1	4.14
	Alternator	171.89	1	171.89
	Premium Gasoline (gallons)	5.99	15	89.78
	Fuel Pressure Regulator	379.70	1	379.70
	Fuel Pump	141.90	1	141.90
	· ·	0.00	1	0.00
	Other:			
	Gas Tank Clean & Seal	292.50	1	292.50
	***Steam, Flush, remove debris, & redcoat	0.00	1	0.00
				0.00
				0.00
	Shop Supplies		3%	245.10
	Labor Rate	95.00	86	8170.00
	Machining Rate	110.00	0	0.00
	OTHER	₹		292.50
	PARTS	1	*	\$1,958.99
	LABOR	l		\$8,415.10
	TAX		, <u>\$</u>	117.54

TOTAL AMOUNT DUE:

\$10,784.12

EDL SERVICES, LLC

DATE	BODY SHOP - DESCRIPTION	HOURS
9/12	Diagnose overheating issue idle speed at 850rpm, factory calls for 450rpm. Disassemble wiring harness to locate and fix diagnostic plug for EFI system. Re-install wiring harness after located the connection wire with previously removed USB connector. Research reprogramming ECU to proper	6.5
9/19 9/20	engine idle speed. Install adapter calbe to ECU wiring harness. Troubleshooting ECU system tune, tuning adjustments from software, building fuel mapping curve, and test driving accordingly.	2 7
10/18	Further tuning and troubleshooting after reviving the existing faulty Holley ECU. Diagnose fuel pressure issue and removed fuel pump.	6.5
10/20	Cut new AN fuel lines, re-wire fuel pump, install new fuel line fittings, and started building retainer bracket for fuel lines above the exhaust.	3.5
10/26	Contacted Holley customer support and remotely tuned ECU fuel system creating fuel mapping chart. Work with Holley support to resolve stumbling issue.	5
10/27	Diagnose failing vacuum advance and troubleshoot.	4
11/7	Install new throttle pedal and fixed linkage	1.5
11/9	Troubleshoot timing chain for potential stretch/failing all good. Set and adjust timing. Test drove fuel supply issue. Troubleshooting	6.5
11/10	fuel supply issue. Talking on phone with Holley representative regarding fuel pressure regulator compatabilities with ECU on car.	1
11/16	Installed new fuel pressure regulator.	1
11/17	Troubleshooting fuel pressure regulator with ECU on car, talking to Holley representatives.	8
11/22	On the phone with Holley representative	0.5
	Remove exhaust, remove and inspect O2 sensor failed/no longer functioning. Replaced O2 sensor, reinstalled exhaust, reprogrammed and test drove fuel pressure irregularities.	5.5
12/6	Troubleshoot fuel pressure issue. More test driving and tune adjustments. Re-wired fuel pump and re-wired fuel relay system.	5.5
	Test drove fuel pressure problem persists. Car towed back to shop.	3
	Removed gas tank, found loose metal pieces within the fuel tank. Debris appears to be welding globs from previous work on fuel system. Send tank out for thorough cleaning and reconditioning.	1.5
	Total Hours	68.5

EDL SERVICES, LLC

DATE	BODY SHOP - DESCRIPTION	HOURS
12/12 12/13	Installing refurbished fuel tank, reinstall sending unit, reconnecting fuel lines Finished installing fuel pump, made new brackets to secure fuel lines, re-wired fuel pump and reassembled interior. Took car for 1 hour long	8 7
12/14	test drive satisfactory. Filled gas tank with premium gasoline. Final test drive to ensure all issues have been resolved all good.	2.5
,		
	Total Hours	17.5