

# Preliminary Supplement 1 with Summary

Customer: [REDACTED]

Job Number:

1989 FERRARI 328GTS RED

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	Rpr	Air conditioning Note: AC System is empty and will not operate. It is possible there may be a leak that will need to be located and repaired prior to recharging the system. F40 will not be able to service AC as it is R12 freon. This repair will need to be sublet out					
2	#	Rpr	Timing belt / engine oil service				16.0	
3	#	Repl	Engine oil filter		1	33.70		
4	#	Repl	Engine oil		1	68.00		
5	#	Repl	Drain plug gasket		1	1.33		
6	#	Repl	Timing belts		2	68.08		
7	#	Repl	Timing belt tensioner pulleys		2	131.92		
8	#	Repl	Air Conditioning belt		1	51.07		
9	#	Repl	Water pump belt		1	26.06		
10	#	Repl	Water pump / AC idler bearings		2	52.12		
11	#	Repl	Alternator belt		1	16.65		
12	#	Repl	Water pump & gaskets		1	661.15		
13	#	Repl	Coolant		1	36.00		
14	#	Repl	Shift knob		1	66.50		
15	#	Rpr	LT Door inside handle Note: Repair peeling leather				0.5	
16	#	Rpr	Balance wheels				1.0	
17	#	Repl	Front hood support Note: Repair mount braces & install support		1	135.87	0.5	
18	#	S01 Repl	Front hood support shoulder bolts		2	98.54		
19	#	S01 Repl	Estimated Parts shipping cost		1	30.20		
20	#	Rpr	Steering binding Note: Steering binds very 180 degrees, possibly "U" Joints in shaft. Will be necessary to remove shaft to inspect and service joints. Part replacement may be necessary...Inspection of shaft found "U" Joints in need of lubrication only.				1.0	
21	#	S01 Rpr	Front seats Note: LT Front seat slide is frozen in the most rearward position, the rt seat moves although very difficult. Both seats will need to be removed to repair. LT Seat will need to be unlocked to slide forward to gain access to the rear bolts that hold seat in place. Unknown at this time what labor time will be for this repair 2 hours included in this estimate. Supplement notes: Once seats had been removed shop tech was able to clean and lube passenger seat tracks to operat properly although it was necessary to remove and disassemble driver outside seat track to remove a ball bearing that had become undone from seat track and lodged in track. Cleaned and lubed drivers tracks and reinstalled seats to vehicle.				3.5	
22	#	Rpr	Full detail Note: Remove wheels & clean inside & out, wash and clen underbody, suspension, engine & transmission, machine buff, polish & wax, brush paint touch up chips, clean interior & trunk area, shampoo carpets and floor mats				8.0	
23	#	S01 Repl	Fuel door bib Note: Bib has a tear		1	53.04		
<b>SUBTOTALS</b>						<b>1,530.23</b>	<b>30.5</b>	<b>0.0</b>

HADSEL BILL

Preliminary Supplement 1 with Summary

Customer: [REDACTED]

Job Number:

1989 FERRARI 328GTS RED

**ESTIMATE TOTALS**

Category	Basis		Rate	Cost \$
Parts				1,530.23
Body Labor	30.5 hrs	@	\$ 120.00 /hr	3,660.00
Body Supplies	30.5 hrs	@	\$ 5.00 /hr	152.50
Subtotal				5,342.73
Sales Tax	\$ 5,342.73	@	6.3500 %	339.26
<b>Grand Total</b>				<b>5,681.99</b>

# Preliminary Supplement 1 with Summary

Customer: [REDACTED]

Job Number:

1989 FERRARI 328GTS RED

## SUPPLEMENT SUMMARY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
<b>Changed Items</b>							
18	#	Repl	Estimated Parts shipping cost	1	-20.00		
19	#	S01 Repl	Estimated Parts shipping cost	1	30.20		
20	#	Rpr	Front seats			-2.0	
NOTE: LT Front seat slide is frozen in the most rearward position, the rt seat moves although very difficult. Both seats will need to be removed to repair. LT Seat will need to be unlocked to slide forward to gain access to the rear bolts that hold seat in place. Unknown at this time what labor time will be for this repair 2 hours included in this estimate.							
21	#	S01 Rpr	Front seats			3.5	
NOTE: LT Front seat slide is frozen in the most rearward position, the rt seat moves although very difficult. Both seats will need to be removed to repair. LT Seat will need to be unlocked to slide forward to gain access to the rear bolts that hold seat in place. Unknown at this time what labor time will be for this repair 2 hours included in this estimate. Supplement notes: Once seats had been removed shop tech was able to clean and lube passenger seat tracks to operat properly although it was necessary to remove and disassemble driver outside seat track to remove a ball bearing that had become undone from seat track and lodged in track. Cleaned and lubed drivers tracks and reinstalled seats to vehicle.							
<b>Added Items</b>							
18	#	S01 Repl	Front hood support shoulder bolts	2	98.54		
23	#	S01 Repl	Fuel door bib	1	53.04		
NOTE: Bib has a tear							
<b>SUBTOTALS</b>					<b>161.78</b>	<b>1.5</b>	<b>0.0</b>

## TOTALS SUMMARY

Category	Basis	Rate	Cost \$
Parts			161.78
Body Labor	1.5 hrs @	\$ 120.00 /hr	180.00
Body Supplies	1.5 hrs @	\$ 5.00 /hr	7.50
Subtotal			349.28
Sales Tax	\$ 349.28 @	6.3500 %	22.18
<b>Total Supplement Amount</b>			<b>371.46</b>
<b>NET COST OF SUPPLEMENT</b>			<b>371.46</b>

**F40 RESTORATION**  
464 PORTLAND COBALT RD, PORTLAND, CT  
06480  
Phone: (860) 342-2427  
FAX: (860) 342-1094

Workfile ID: 0397121f  
PartsShare: 6s3VPK  
Federal ID: FED TAX#  
State ID: 03-0459234  
CT TAX#  
1848860-000

**Preliminary Supplement 1 with Summary**

**Customer:** [REDACTED]

**Job Number:**

Written By: Craig Scott

**Insured:** [REDACTED]  
**Type of Loss:**  
**Point of Impact:**

**Policy #:**  
**Date of Loss:**

**Claim #:**  
**Days to Repair:** 0

**Owner:**  
[REDACTED]

**Inspection Location:**  
F40 RESTORATION  
464 PORTLAND COBALT RD  
PORTLAND, CT 06480  
Repair Facility  
(860) 342-2427 Day

**Insurance Company:**

**VEHICLE**

1989 FERRARI 328GTS RED

**VIN:** ZFFXA20A4K0082867  
**License:**  
**State:**

**Interior Color:**  
**Exterior Color:** RED  
**Production Date:**

**Mileage In:** 26,790  
**Mileage Out:**  
**Condition:**  
**Vehicle Out:**  
**Job #:**



07:51:

**MC SALE**

R  
R  
P  
R  
R  
R  
R  
P  
R  
R  
R  
R  
R  
R  
F

**Invoice**

14 Allen Dr.  
P.O. Box 146  
CT 06755

Date	Invoice #
8/8/2016	514

Bill To
William Hadsel 174 Russell rd Hurley, Ny 12443

ODOMETER / PLATE		VIN #	COLOR/TRIM	VEHICLE / MODEL	
#FYK5427		0082867	Red/Tan	89 Ferrari 328gts	
Qty	Description	Rate	Amount		
2	Check engine running misfire. stalls at idle. diagnose and perform fuel trim test.	140.00	280.00T		
	Protection relay	226.80	226.80T		
1	Smoke tested engine for vaccum leaks.	140.00	140.00T		
1	OEM Bosch O2 sensor	197.85	197.85T		
3	Install O2 sensor. Check function of all other sensors. Replace protection relay and fuse assembly. Check and adjust fuel trim.	140.00	420.00T		
	Tech Noted during road test steering feels notchy and wheel reluctant to return to center. Possible bend in steering rack. This issue should be addressed at a future time.				
	Sales Tax	6.35%	80.31		

		<b>Total</b>	\$1,344.96
		<b>Payments/Credits</b>	\$0.00
		<b>Balance Due</b>	\$1,344.96

Phone #
860-355-6990

# CONTINENTAL AUTO BODY

464 PORTLAND COBALT RD, PORTLAND, CT 06480

Phone: (860) 342-2427

Fax: (860) 342-1094

## Preliminary Estimate

**Customer: EICHACKER, FRANKLIN**

Written By: craig scott

Insured: EICHACKER, FRANKLIN

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact:

**Owner:**

EICHACKER, FRANKLIN  
80 HOLLISTER WAY  
GLASTONBURY, CT 06033  
(860) 633-4468 Day

**Inspection Location:**

CONTINENTAL AUTO BODY  
464 PORTLAND COBALT RD  
PORTLAND, CT 06480  
Repair Facility  
(860) 342-2427 Day

**Insurance Company:**

## VEHICLE

Year: 1989

Body Style: 2D

VIN: ZFFXA20A4K0082867

Mileage In: 21469

Make:

Engine:

License:

Mileage Out:

Model: FERR 328 GTS

Production Date:

State:

Vehicle Out:

Color: Int:

Condition:

Job #:

QTY.	PART NO. AND DESCRIPTION	PRICE
------	--------------------------	-------

*Paid in Full*  
*Thank you!*

**I.F.S. INC.**  
14 BRISTOL DRIVE, UNIT F  
SOUTH EASTON, MA 02375  
Phone: (508) 238-4224 Fax: (508) 238-4224

4454

NAME <i>Los Compton</i>	CUSTOMER'S ORDER NO.	DATE <i>2.17.09</i>
ADDRESS <i>215 BLUFF POINT RD</i>	ORDER WRITTEN BY <i>LT</i>	PROMISED  A.M. P.M.
CITY, STATE, ZIP <i>J. GLASTONBURY CT 06033</i>	<i>860 306-9774</i>	
HOME PHONE	BUS. PHONE <i>860 678 3135</i>	EXT.
YEAR, MAKE AND MODEL <i>1989 928 GT</i>	LICENSE NUMBER <i>860 306 9774</i>	ODOMETER IN
SERIAL NUMBER <i>82867</i>	MOTOR NUMBER	ODOMETER OUT
TERMS		

DESCRIPTION OF WORK		AMOUNT	
<input type="checkbox"/> LUBE <input type="checkbox"/> CHANGE OIL <input type="checkbox"/> OIL FILTER <input type="checkbox"/> TUNE-UP <input type="checkbox"/> TRANS. <input type="checkbox"/> DIFF.			
<i>REPAIR FRONT LOWER SPINDLE - (CRACKED)</i>		<i>N/C</i>	
<i>REMOVE AND SUBLET REBUILD of STATION CHARGES BATTERY</i>		<i>225 00</i>	
<i>PICK UP USHILLS FSS</i>		<i>N/C</i>	
<i>DELIVERY USHILLS FSS</i>		<i>170 00</i>	
<b>TOTAL PARTS</b>		<b>LITERS/GALS. OF GAS @</b>	<b>TOTAL LABOR</b> <i>240 00</i>
<b>ACCESSORIES</b>		<b>LITERS/QTS. OF OIL @</b>	<b>TOTAL PARTS</b>
		<b>kg/LBS. OF GREASE @</b>	<b>ACCESSORIES</b>
			<b>GAS, OIL AND GREASE</b>
			<b>SUBLET REPAIRS</b> <i>225 00</i>
I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.		<b>EPA / WASTE DISPOSAL</b>	
		<i>Tow SVC.</i>	<i>170 00</i>
		<b>TAX</b>	
<b>TOTAL ACCESSORIES</b>		<b>SAVE OLD PARTS?</b> <input type="checkbox"/> YES <input type="checkbox"/> NO	<b>TOTAL</b> <i>635 00</i>
		<b>SIGNATURE</b>	<b>THANK YOU</b>



QTY.	PART NO. AND DESCRIPTION	PRICE			
3	2214 SEAL RING	2	50	7	50
2	RED LINS DIFF ADDITIVE	9	75	19	50
2	PRESSON COOLANT	18	90	37	80
2	LMA BRAKE FLUID	9	75	19	50
1	118006 AIR FILTER	52	80	52	80
2	205 55 V116 SX MXX3	166	40	332	80
2	225 50 V12 SX MXX3	248	30	496	60

PAID 6.8.08

02108 4197

**I.F.S. INC.**  
**14 BRISTOL DRIVE, UNIT F**  
**SOUTH EASTON, MA 02375**  
**Phone: (508) 238-4224 Fax: (508) 238-4224**

NAME <i>Los Concha</i>		CUSTOMER'S ORDER NO.	DATE <i>5-22-08</i>
ADDRESS <i>265 BLUFF POINT RD</i>		ORDER WRITTEN BY <i>SLT</i>	PROMISED  A.M. P.M.
CITY, STATE, ZIP <i>S. GLASTONBURY CT</i>			
HOME PHONE <i>860 633 7736</i>	BUS. PHONE <i>860 306 9774</i>	EXT.	ODOMETER IN
YEAR, MAKE AND MODEL <i>1989 328 GTs</i>		LICENSE NUMBER <i>607MYD CT</i>	ODOMETER OUT <i>20114</i>
SERIAL NUMBER <i>82867</i>	MOTOR NUMBER	TERMS	

DESCRIPTION OF WORK				AMOUNT	
<input type="checkbox"/> LUBE	<input type="checkbox"/> CHANGE OIL	<input type="checkbox"/> OIL FILTER	<input type="checkbox"/> TUNE-UP	<input type="checkbox"/> TRANS.	<input type="checkbox"/> DIFF.
<i>OIL SERVICES: Motor, Gearbox, COOLANT</i>					
<i>FLUSH BRAKE FLUID &amp; BLEED</i>					
<i>ADJUST CLUTCH AND PARKING BRAKE</i>					
<i>REMOVED DRIVERS DOOR PANEL + REPAIRED WINDOW TRAIL</i>					
<i>MOUNT &amp; BALANCE 4 NEW TIRES</i>				<i>200</i>	<i>00</i>
<i>4 WHEEL ALIGNMENT</i>				<i>200</i>	<i>00</i>
<i>COMPLETE DETAIL</i>				<i>200</i>	<i>00</i>

(MAY BE CONTINUED ON OTHER SIDE)		<b>TOTAL PARTS</b>		<b>LITERS/GALS. OF GAS @</b>		<b>TOTAL LABOR</b>		<i>720</i>	<i>00</i>			
<b>ACCESSORIES</b>		<b>8</b>		<b>LITERS/QTS. OF OIL @ GTX</b>		<i>20/50</i>	<i>28</i>	<i>00</i>	<b>TOTAL PARTS</b>	<i>966</i>	<i>50</i>	
		<b>4</b>		<b>kg/LBS. OF GREASE @</b>		<i>75/90c</i>	<i>34</i>	<i>00</i>	<b>ACCESSORIES</b>			
<div style="border: 1px solid black; border-radius: 50%; padding: 10px; text-align: center;"> <i>Paid in Full</i>  <i>Thank you!</i> </div>								<b>GAS, OIL AND GREASE</b>	<i>62</i>	<i>00</i>		
								<b>TOW SUBLET REPAIRS</b>	<i>1120</i>	<i>00</i>		
								<b>EPA / WASTE DISPOSAL</b>	<i>30</i>	<i>00</i>		
								<b>SHIPPING</b>	<i>40</i>	<i>00</i>		
								<b>out of STATE DELIVERY</b>				
<b>TOTAL ACCESSORIES</b>				<b>SAVE OLD PARTS?</b>		<input type="checkbox"/> YES <input type="checkbox"/> NO		<i>62</i>	<i>00</i>	<b>TOTAL</b>	<i>2938</i>	<i>50</i>
				SIGNATURE		<i>Phonix 5-23-08</i>				<b>THANK YOU</b>		





## REPAIR ORDER

DATE

JOB NUMBER

JOB NAME

QTY	PART NO. AND DESCRIPTION	PRICE
1	163989 R/M SEAL	47 25 47 25
1	134714 SEAL	19 95 19 95
1	CLUTCH OILWHL KIT	8 50 8 50
1	120482 DISC	450 37 450 37
1	121562 PRESSURE PLATE	498 95 498 95
1	100849 RELEASE BOWL	121 50 121 50
1	126853 NUT	28 90 28 90
1	103877 PILOT RING	23 65 23 65
2	105206 TENSIONER BOWL	131 25 262 50
2	111334 CAM BOLT	23 55 59 90
1	100564 CHECK VALVE	38 00 38 00
1	111742 OIL FILTER	25 00 25 00
2	105038 BRAKING	42 00 84 00
1	121405 PULLEY	126 00 126 00
1	121385 CATALYTIC COVER	800 00 800 00
1	118006 AIR FILTER	40 00 40 00
1	105046 BOLT	43 70 43 70
1	130493 BOLT	12 90 12 90
1	121655 BOLT	22 50 22 50
2	01622 SEAL RING	2 25 6 75
1	151342 GASKET	8 75 3 75
TOTAL PARTS		

(MAY BE CONTINUED ON OTHER SIDE)

## ACCESSORIES

1	119409 GASKET	4 95 4 95
1	132453 SEAL	39 90 39 90
1	134956 GASKET	5 45 5 45
2	121788 16MM WIND CLIP	4 50 9 00
1	121788 CAM CV GASKET	53 55 53 55
3	R-12 FRODO	70 10 210 00
TOTAL ACCESSORIES		3046 92

## I.F.S. INC.

21 Hampden Drive Unit 10  
SOUTH EASTON, MA 02375  
(508) 238-4224

2501

860 678 7414

NAME JOSEPH D. CONPONA	CUSTOMER'S ORDER NO.	DATE 4-16-02
ADDRESS 265 BLUFF POINT RD.	ORDER WRITTEN BY JCT	PROMISED A.M. P.M.
CITY, STATE, ZIP S. GLASTONBURY, CT 06033	HOME PHONE 860-633 7736	BUS PHONE 860 678 3235
YEAR, MAKE AND MODEL 1989 308 LTS	EXT.	ODOMETER 16871
SERIAL NUMBER 52667	MOTOR NUMBER	LICENSE NUMBER 607M42
TERMS		

## DESCRIPTION OF WORK

## AMOUNT

☐ LUBE ☐ CHANGE OIL ☐ OIL FILTER ☐ TUNE-UP ☐ TRANS. ☐ DIFF.

EMISSIONS FAILURE - CAMSHAFT TIMING  
CAMSHAFT BOLT SERVICES  
REPLACED CLUTCH ASSY.  
REPLACED R/M AND CLUTCH SHAFT SEALS  
REPLACED CATALYTIC CONVERTER  
GIL SERVICES - COMPLETE, ALL FLUIDS  
AIR CONDITIONING SERVICES

ALSO 12/0 2502 AND WASH SHUTS

LITERS/GALS. OF GAS @

TOTAL LABOR 2125 00

LITERS/QTS. OF OIL @ 12/0 20/50

TOTAL PARTS 3271 92

kg/LBS. OF GREASE @ 75 90 C

ACCESSORIES

WASTE OIL REMOVAL

GAS, OIL AND GREASE 111 50

SUBLET REPAIRS 22 00

EPA/WASTE DISPOSAL

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

SHIPPING 80 00

DELIV. OF STATS

SIGNATURE

111 50

TOTAL  
THANK YOU

5610 42

## REPAIR ORDER

**DATE**

## CONCLUSION

**2000-2001**

[illegible]

**I.F.S. INC.**  
21 Hampden Drive Unit 10  
SOUTH EASTON, MA 02375  
(508) 238-4224

2502

NAME <b>Josaph D CONDONA</b>						CUSTOMER'S ORDER NO.	DATE 4-16-02
ADDRESS <b>965 BLUFF POINT RD</b>						ORDER WRITTEN BY <b>JLT</b>	PROMISED A.M. P.M.
CITY, STATE, ZIP <b>S. GLASTONHURST, CT 06073</b>							
HOME PHONE <b>860 633 7736</b>				BUS. PHONE <b>860 678 8135</b>	EXT.	ODOMETER <b>16871</b>	
YEAR, MAKE AND MODEL <b>860 306 9774 C</b>						LICENSE NUMBER <b>667 MYO</b>	
SERIAL NUMBER <b>E2867</b>				MOTOR NUMBER	TURNS		
DESCRIPTION OF WORK						AMOUNT	
<input type="checkbox"/> LUBE	<input type="checkbox"/> CHANGE OIL	<input type="checkbox"/> OIL FILTER	<input type="checkbox"/> TUNE-UP	<input type="checkbox"/> TRANS.	<input type="checkbox"/> DIFF.		
<b>ALSO R/O 2501</b>							
____ LITERS/GALS. OF GAS @						TOTAL LABOR	
____ LITERS/QTS. OF OIL @						TOTAL PARTS	
____ kg/LBS. OF GREASE @						ACCESSORIES	
WASTE OIL REMOVAL						GAS, OIL AND GREASE	
						SUBLET REPAIRS	
I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in care in case of fire, theft or any other cause beyond your control.						EPA/WASTE DISPOSAL	
						TAX	
SIGNATURE _____						TOTAL THANK YOU	

# CONTINENTAL AUTO BODY

464 PORTLAND COBALT RD, PORTLAND, CT 06480

Phone: (860) 342-2427

Fax: (860) 342-1094

## Preliminary Estimate

Customer: EICHACKER, FRANKLIN

Line	Operation	Description	Qty	Extended Price \$	Labor	Paint
1 #	Rpr	Lube,oil,filter service				
2 #	Repl	Oil filter	1	18.99		
3 #	Repl	Engine oil	10	60.00		
4 #	Repl	Top off all fluids	1			
5 #	Rpr	Check belts & adjust "all in good shape"				
6 #	Rpr	Check brakes "all good"				
7 #	Rpr	Check tires and air pressure "tires all good"				
8 #	Rpr	Check & adjust fuel door				
9 #	Repl	Labor and shop supplies	1	16.00	3.5	
SUBTOTALS				94.99	3.5	0.0

### ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			94.99
Body Labor	3.5 hrs @	\$ 95.00 /hr	332.50
Subtotal			427.49
Sales Tax	\$ 427.49 @	6.0000 %	25.65
<b>Grand Total</b>			<b>453.14</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>453.14</b>

**NOTICE: YOU HAVE THE RIGHT TO CHOOSE THE LICENSED REPAIR SHOP WHERE THE DAMAGE TO YOUR MOTOR VEHICLE WILL BE REPAIRED.**

CCC Pathways - A product of CCC Information Services Inc.

03/28/2002 11:32 5062384224

IFS

Red lru 20/50

John L. Tirrell, President

800

DIAG

Belt

Clutch

Labor 2125

Part 3271 92

oil 111 55

Shipping 80

## NOTE:

This Ferrari needs 15,000 Major Service.

This service includes:

Cylinder head retorque.

Valve adjustment.

Replacement of the spark plugs and ignition wires.

Checking and cleaning of the distributor caps.

Replacement of the fuel filter.

Cleaning of the Fuel injection.

Checking of the brakes and cleaning of the calipers if needed.

The camshaft oil seals should be replaced. There would be a substantial savings in labor if done at the time of the camshaft belt service in lru of the fact that the camshaft covers and belts will be disassembled for the service noted above.

Estimate for above repairs, taking into account that I have no prior history of the vehicle.

Clutch: \$2050.00

Belts: \$1,200.00

Major Service \$2,500.00

Respectfully,

John L. Tirrell



IFS INC.

Bo.  
764 281 5237

860 653 0032

Patrick

Approved

678 3232

860

7414



*John L. Tirrell, President*

*Independent Ferrari Service, Inc.*

Continental Auto Body

3/26/02

Wayne Carini

1989 Ferrari 328

Estimate for service.

**Complete clutch replacement:**

Remove left rear tire and wheel house.

Remove bellhousing.

Remove clutch pressure plate and disc.

Remove flywheel and sublet resurface machining.

Remove and replace rear crankshaft seal.

Clean bellhousing and replace clutch shaft seal.

Replace pilot bearing.

Replace bellhousing O rings.

Reassemble entire package.

Adjust clutch linkage.

Adjust pedal height.

Add gearbox oil.



*John L. Tirrell, President*

*Independent Ferrari Service, Inc.*

**Camshaft belt service:**

Remove right rear wheel and wheelhouse.

Evacuate air conditioning.

Drain coolant.

Remove alternator and water pump belts.

Remove air conditioning compressor and belt.

Remove both timing covers and shields.

Set up timing on motor for belt removal.

Remove both timing belts and tensioners.

Disassemble, clean and rebuild tensioner assemblies with new bearings and lubricant.

Replace timing belts and rebuilt tensioner assemblies.

Set camshaft timing.

Reinstall all related parts.

Replace and tension water pump and alternator belts.

Service air conditioning.

Refill coolant.

Bleed coolant system including heater boxes.

Road test vehicle.





*John L. Tirrell, President*

*Independent Ferrari Service, Inc.*

**NOTE:**

**This Ferrari needs 15,000 Major Service.**

**This service includes:**

**Cylinder head retorque.**

**Valve adjustment.**

**Replacement of the spark plugs and ignition wires.**

**Checking and cleaning of the distributor caps.**

**Replacement of the fuel filter.**

**Cleaning of the Fuel injection.**

**Checking of the brakes and cleaning of the calipers if needed.**

**The camshaft oil seals should be replaced. There would be a substantial savings in labor if done at the time of the camshaft belt service in lieu of the fact that the camshaft covers and belts will be disassembled for the service noted above.**

**Estimate for above repairs, taking into account that I have no prior history of the vehicle.**

**Clutch: \$2050.00**

**Belts: \$1,200.00**

**Major Service \$2,500.00**

**Respectfully,**

**John L. Tirrell**

