

"CONCOURSE QUALITY, HOBBYIST PRICE"

Marti Auto Works

www.martiauto.com
13238 W Butler Drive
El Mirage, AZ 85335
Phone (623) 935-2558
Fax (623) 935-2579

DELUXE MARTI REPORT®



Proud to display this symbol

Copyright Kevin Marti 2024

Thank you for your interest in our services. We have determined the following information for your vehicle from the Ford Database we have:

12345678901234567890123456789012345678901234567890123456789012345678901234567890
8F01J207298 U 2K 2 14F9273 TEHF 652 5F2 2 38F555 8

DOOR DATA PLATE INFORMATION

Serial Number **8F01J207298**

8 1968
F Built at Dearborn
01 Mustang 2-Door Hardtop
J 302-4V V-8 Engine
207298 Serial Number of this Ford scheduled for production at Dearborn

65A Mustang 2-Door Hardtop
U Tahoe Turquoise Paint, Ford #1070-A
2K Aqua Vinyl Standard Bucket Seats
14F Scheduled for build June 14, 1968
38 Pittsburgh DSO (District Sales Office)
7 3.25 Conventional Rear Axle
5 Four-Speed Manual Transmission

ORDER TYPE: STOCK

DSO ITEM #: 9273

DEALER #: 14F555

JACK BEASLEY FORD SLS
1901 MARGARET AVE
ALTOONA PA 16603

Your vehicle was equipped with the following features:

- GT Equipment Group
- Visibility Group
- F70X14 Wide Oval White Sidewall Nylon Tires
- AM Radio

Your vehicle was actually produced on June 17, 1968 -- three days behind schedule.

Kevin Marti

Kevin Marti



IMPORTANT DATES

ORDER RECEIVED: 05/29/68
CAR SERIALIZED: 06/04/68
BUCKED: 06/12/68
SCHEDULED FOR BUILD: 06/14/68
ACTUALLY BUILT: 06/17/68
RELEASED: 06/17/68
SOLD: 09/21/68

STATISTICS

Your vehicle was one of:

7,217 With this Paint Code
4,796 With these Paint/Trim Codes
2,851 With these Engine/Transmission Codes
3,714 Ordered from this DSO
4,766 With GT Equipment Group

For the 1968 Mustang 2-Door Hardtop

Barron's Automotive Repair Inc.

701 W. 7th Street

Auburn, IN. 46706

Phone: 260-927-8202 Fax: 260-333-7199

INVOICE**47657****INVOICE**

Printed Date: 10/04/2024

Work Completed: 10/04/2024

1968 Ford - Mustang -

Lic # : 45B4919

Odometer In : 110066

Home

VIN # : 8F01J2072 98U2K214

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Carburetor Kit 25572	1.00	90.06	90.06	MECHANICAL DIAGNOSTIC - SITTING OVERNIGHT, OR COLD, VEHICLE WILL CRANK NO START UNLESS STARTING FLUID IS USED	0.30	66.35
Washer Fluid -20° WV8001288	1.00	0.00	n/c			
CONV OIL 10W30 5 QT 5 QT F630-5QT	1.00	33.62	33.62	CHOKE IS NOT WORKING PROPERLY AND HAS BEEN TURNED OFF. NO HEAT COMING FROM MANIFOLD, SUSPECT BLOCKED STOVE PIPE. ACCELERATOR PUMP IS NOT OPERATING AND FOUND MULTIPLE PIECES OF LINKAGE HOOKED ONTO THE PUMP BEING IN THE WRONG ORIENTATION.		
RISLONE ENGINE OIL S 11 O 4405	1.00	17.70	17.70	WILL NEED TO REBUILD CARB AND FIND ALL REQUIRED PARTS.		
OIL FILTER LD 1 EA CQBLU 85515	1.00	6.08	6.08	(CUSTOMER APPROVED)		
SPARK PLUG-COPPER 1 EA AUTLT 45	8.00	3.75	30.00	MECHANICAL DIAGNOSTIC - BRAKE LIGHTS INOP? ANOTHER SHOP HAS REPLACED ALL BULBS AND SWITCH?	0.30	66.35
V-BELT-TOP COG 1 EA 1 EA CQDAY 15405	1.00	18.38	18.38			
Carburetor Gasket 60046	2.00	4.35	8.70	BRAKE PEDAL BUSHINGS ARE INCORRECT FOR THE VEHICLE AND PEDALS ARE NOT OPERATING CORRECTLY. RECOMMEND TO REPLACE BUSHINGS AND THEN CHECK OPERATION OF SWITCH.		
Brake Light Switch SLS69	1.00	12.11	12.11	(CUSTOMER APPROVED)		
Shop Supplies			18.59	CHECK TO SEE IF IT NEEDS A TUNE UP		nc
				IGNITION LOOKS NEWER BUT PLUGS WORN. RECOMMEND TO REPLACE.		
				(CUSTOMER APPROVED)		
				CHECK TO SEE IF OIL NEEDS CHANGED		nc
				CHECK BRAKES, THE PEDAL FEELS HARD?		nc
				BRAKES IN GOOD WORKING CONDITION. JUST NEED ADJUSTMENT. BRAKES ARE NON-POWER AND WILL NOT BE AS EASY TO PRESS AS POWER BRAKES.		
				CHECK MIRROR - ABLE TO TIGHTEN?		nc
				WAS ABLE TO TIGHTEN INSIDE MIRROR BUT OUTSIDE MIRRORS CANNOT BE ADJUSTED. WILL NEED TO BE REPLACED FOR LOOSENESS. RECOMMEND BODY SHOP.		
				TOP OF AIR CLEANER IS IN THE BACK SEAT		nc
				CLEAN CARB	1.50	187.50
				TUNE CARB AND IGNITION TIMING	1.50	187.50
				LUBE, OIL, AND FILTER	0.50	32.50
				Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Perform basic safety inspection.		
				SPARK PLUG REPLACEMENT	1.20	150.00
				REPLACE ACCESSORY BELT	0.50	62.50
				REPLACE BRAKE PEDAL BUSHINGS	0.25	31.25

Barron's Automotive Repair Inc.
701 W. 7th Street
Auburn, IN. 46706
Phone: 260-927-8202 Fax: 260-333-7199

INVOICE

47657

INVOICE

Printed Date: 10/04/2024

Work Completed: 10/04/2024

Hucker, Tom

1968 Ford - Mustang -

Lic # : 45B4919

Odometer In : 110066

Home 260-387-3664

VIN # : 8F01J2072 98U2K214

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
				BRAKE PEDAL HARDWARE		31.57
				ANTIFREEZE NOTED AT -45*		
				Hazardous Materials		10.83
				Taxes		
				Regular Rate		15.17

[Payments -]

PAYMENT IS REQUIRED AT TIME OF SERVICE.

NET 15 DAYS FOR ALL PREAPPROVED COMMERCIAL ACCOUNTS.

A Mechanics Lien is hereby acknowledged on above vehicle to secure the amount of repairs. Parts are warranted by manufacturer's guidelines, labor 90 days through Barron's Automotive Repair. Warranty work to be performed at Barron's Automotive Repair and cannot exceed the original cost of repair. Any returned checks will incur a \$25 fee. Estimates are valid for 30 days. Estimates older than 30 days are void.

Labor:	783.95
Parts:	235.24
Sublet:	31.57
HazMat:	10.83
Sub:	1,061.59
Tax:	15.17
Total:	\$1,076.76
Bal Due:	\$1,076.76

Vehicle Received: 10/4/2024

Customer Number : 6942

Signature _____ Date _____

Stemen Align & Brake

3607 N. Wells

Ft. Wayne, IN 46808

(260) 483-4030

Monday - Friday 8:00 AM to 5:30 PM

Visit us on Facebook

Thank you for your business!

Invoice #14555

Page:1

Phone: 260-333-3661

Vehicle : 1968 Ford Mustang 4.7 L 289 CID V8

Tag/State : /IN

VIN :

Fleet #/Driver :

Created : 9/12/2024 9:05:54 AM EDT

Invoiced : 9/26/2024 1:20:24 PM EDT

Odometer In : 10044

Odometer Out : 10044

Labor/Notes

Technician	Description	Price
BF	Remove and replace lower control arms	\$220.00
BF	Remove and replace idler arm(s)	\$40.00
BF	TWO WHEEL ALIGNMENT	\$119.50
2 WHEEL ALIGNMENT, INCLUDES COMPLETE INSPECTION OF ALL FRONT AND REAR SUSPENSION AND STEERING COMPONENTS. ADJUST CASTER, CAMBER AND TOE IN OF FRONT END TO FACTORY SPECIFICATIONS, STRAIGHTEN STEERING WHEEL IF NEEDED. DOES NOT INCLUDE REPLACEMENT OF ANY WORN OR DAMAGED PARTS.		
BF	Remove and replace bulb	\$20.00
BF	R&R Brake Light Switch	\$60.00
BF	MOUNT AND BALANCE TIRE	\$150.00
MOUNT TIRE ON WHEEL AND COMPUTERIZE SPIN BALANCE. DOES NOT INCLUDE NEW VALVE STEM.		

Parts

Code	Description	Condition	Unit Price	Price
	Box Headlight Bulb		\$28.64	\$57.28
	Standard Ignition Brake Light Switch		\$16.14	\$16.14
	NAPA Chassis Parts Control Arm w/ Ball Joint - Lower - Front Suspension		\$69.27	\$138.54
	Precision Steering Idler Arm		\$154.51	\$154.51
	Duralast Sway Bar Link		\$12.78	\$25.56
	Adjustable brake push rod		\$38.75	\$38.75
	Duralast Stoplight Switch		\$23.98	\$23.98
	Hankook Kinergy ST H735		\$89.88	\$359.52
	TIRE DISPOSAL FEE		\$3.50	\$10.50
	VALVE STEM/CORE		\$1.00	\$5.00
	WHEEL WEIGHTS		\$3.00	\$12.00

Labor	\$609.50
Parts	\$471.76
Tires	\$359.52
Shop/Haz-Mat	\$37.80
Charges	\$10.50
Sales Tax	Indiana Sales Tax Rule @ 7%
	\$60.84

Total \$1,549.92

Check #120: \$1,549.92

PAYMENT \$1,549.92
BALANCE DUE \$0.00

Technician Code

BF

Certification #

MGR

TEK AUTOMOTIVE

350 East Van Vleet

Waterloo, IN. 46793

Phone: 260-927-1509 Fax: 260-927-1509

INVOICE**17055**

Org. Est. # 017055

ASE Master Techn

INVOICE

Printed Date: 11/18/2024

1968 FORD - MUSTANG 5.0

Lic # :

Odometer In : 10210

Home

VIN# :

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
PREMIUM FUEL PUMP 360590	1.00	42.55	42.55	IDLES ROUGH AND SURGES Engine idles rough and surges at 45 mph.	160.00
BATTERY CABLE 45125	1.00	22.44	22.44	Check timing - Timing over advanced. Adjust to factory spec 6 deg Check fuel system - Carburetor is running lean. Perform fuel pressure test. Pressure should be 5 - 8 psi	
SENDING UNIT FG86ACQ	1.00	114.79	114.79	Engine only has 2 psi. Fuel pressure low Install new fuel pump. Adjust carburetor.	
HEAT SHIELD 21102700	1.00	15.26	15.26	Fresh air tube to hot air choke is missing. Make new fresh air tube and install new heatshield wrap.	
BRAKE LINE TUBING BR-EZ200-50 Shop Supplies	1.50	3.65	5.48 8.02	FUEL PUMP - Remove & Replace Install new fuel pump due to low pressure. Replace fuel line to pump with new clamps. Recheck pressure after pump replacement 8 Psi	64.00
				SENDING UNIT Replace fuel tank sending unit due to not working properly.	104.00
				BATTERY CABLE Install new negative battery cable due to coming apart. Install new body grounds.	56.00
				Hazardous Materials	11.52

Org. Estimate 618.66 Revisions 0.00 Current Estimate 618.66

Labor:	384.00
Parts:	208.54
HazMat:	11.52
SubTotal:	604.06
Tax:	14.60
Total:	618.66
Bal Due:	\$618.66

[Payments -]

Vehicle Received:

Customer Number : 1581

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. OMOG: I understand that I can have emission service and/or adjustments done elsewhere. I hereby waive this right.

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within _____ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts _____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Signature _____ Date _____