



EDL Services LLC
Antique / Classic Car Repair
 1135 Badder Ave.
 Troy, MI 48083
 (248) 797-8781

Make of Car

1959 El Camino

Invoice #3419



<u>Open Date</u>	<u>Parts</u>	Cost of Parts	Quantity	AMOUNT
8/29/2023	12v Top-Post Battery	183.98	1	183.98
	Accelerator Pedal Pad	123.74	1	123.74
<u>Close Date</u>		0.00	1	0.00
9/1/2023		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
	<u>Other:</u>	0.00	1	0.00
		0.00	1	0.00
				0.00
				0.00
	Shop Supplies		3%	5.70
	<u>Labor Rate</u>	95.00	2	190.00
	<u>Machining Rate</u>	110.00	0	0.00
	OTHER			0.00
	PARTS			\$307.71
	LABOR			\$195.70
	TAX			\$ 18.46
	TOTAL AMOUNT DUE:			\$521.87

EDL SERVICES, LLC

DATE	BODY SHOP - DESCRIPTION	HOURS
8/29	Fully charged battery and load tested it -- no good. Replaced with new one.	1
8/30	Installed gas pedal, test drove it and the pedal fell off. Found replacement pedal, ordered it, and installed when delivered. Road test again and pedal stayed on.	1
Total Hours		2



EDL Services LLC
 Antique / Classic Car Repair
 1135 Badder Ave.
 Troy, MI 48083
 (248) 797-8781

Make of Car _____

1959 El Camino

Invoice #3424



Open Date	Parts	Cost of Parts	Quantity	AMOUNT
9/7/2023	Power Master Starter	317.98	1	317.98
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
	<u>Other:</u>	0.00	1	0.00
		0.00	1	0.00
	Shop Supplies		3%	25.65
	Labor Rate	95.00	9	855.00
	Machining Rate	110.00	0	0.00
	OTHER			0.00
	PARTS			\$317.98
	LABOR			\$880.65
	TAX			\$ 19.08
	TOTAL AMOUNT DUE:			<u>\$1,217.71</u>

EDL SERVICES, LLC

DATE	BODY SHOP - DESCRIPTION	HOURS
9/7	Checked oil pressure and replaced sending unit. Removed started and inspected wiring.	2
9/8	Traced electrical shortage within wiring harness to the oil pressure light and installed a new wire. Installed new starter.	7
Total Hours		9



**SERVICES
LLC.**

EDL Services LLC
Antique / Classic Car Repair
 1135 Badder Ave.
 Troy, MI 48083
 (248) 797-8781

Make of Car

1959 El Camino

Invoice #3454



Open Date	Parts	Cost of Parts	Quantity	AMOUNT
11/8/2023	93 Octane Gasoline	6.59	14	92.19
	Rubber Bump-Stop	19.43	1	19.43
<u>Close Date</u>		0.00	1	0.00
11/14/2023		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
		0.00	1	0.00
	<u>Other:</u>	0.00	1	0.00
		0.00	1	0.00
	Shop Supplies		3%	12.83
	<u>Labor Rate</u>	95.00	4.5	427.50
	<u>Machining Rate</u>	110.00	0	0.00
	OTHER			0.00
	PARTS			\$111.62
	LABOR			\$440.33
	TAX		\$	6.70
	TOTAL AMOUNT DUE:			<u>\$558.64</u>

EDL SERVICES, LLC

DATE	BODY SHOP - DESCRIPTION	HOURS
11/8	Troubleshoot stiff clutch pedal. Removed Clutch Arnature and drilled new hole closer to rotational point. Increased leverage should allow for softer clutch pedal. Reinstalled on car, test drove -- clutch pedal started binding at top.	3
11/13	Add missing bump-stop for the clutch pedal return. Test drove -- resolved. Customer is advised to drive the car regularly to determine if clutch pedal pressure is ideal.	1.5
Total Hours		4.5