



Invoice

Date
Friday, March 1, 2024

Invoice No.	81101
-------------	-------

1964	Oldsmobile	88
		0

Labor Rates: Body \$95.00 | Paint \$95.00 | Trim \$95.00 | Mech \$95.00 | Fab \$95.00

Description	Parts/ Materials	Labor Hours				
		Body	Paint	Trim	Mech	Fab
Perform Mechanical Checklist inspection					4.00	
Remove & replace battery Install battery hold down	227.50				1.00	1.00
Test drive Compression test Evaluate & advise					2.00	
Check hard brake pedal Remove & replace brake booster	156.00				4.00	
Source parts & estimate repairs & upgrades					3.00	
Repair & weld aftermarket front disc brake caliper brackets	7.80				4.00	1.50
Caliper dust seals are cracked Remove & replace calipers (2)	130.00				1.00	
Clean & re-pack front wheel bearings Check wheel seals	3.90				2.00	
Remove & replace wheel cylinders	65.00				4.00	
Bleed & adjust brakes Check master cylinder for leaks	10.40				2.00	
Remove & replace harmonic balancer seal Inspect balancer	39.00				4.00	
Remove & replace transmission pan gasket	84.50				2.50	
Remove & replace valve covers (new) & valve cover gaskets	169.00				2.00	
Install fuel pump block off plate	26.00				0.25	
Remove & replace spark plugs & spark plug wires	143.00				2.50	
Electronic ignition (new distributor) upgrade	497.90				2.00	
Remove & replace fuel filter	26.00				1.50	
Repair fuel gauge sending unit ground wire	3.25				1.00	
Remove & replace rear pinion gasket & seal	39.00				4.00	
Remove & replace rear axle seals	41.60				1.00	
Re-fill gear oil	37.70				0.25	
Replace coolant overflow bottle Source part or fab	123.50				3.00	1.00
Install battery hold down Source part or fab	39.00				2.00	1.00
Remove & replace high beam bulbs (2)	45.50				1.50	
Repair faulty tail light wiring Remove & replace tail light sockets	110.50				4.50	
Remove & replace or repair turn signal switch Repair horn	227.50				2.00	
Adjust reverse light switch & re-test					1.50	
Remove & replace radio (modern Bluetooth upgrade) & new speaker	715.00				8.00	
Repair exhaust leak Re-surface exhaust (2) manifolds	58.50				4.00	
Wrap / shield transmission cooler lines	110.50				1.50	
Clean , prep & re-attach convertible top felt weatherstripping	13.00				3.50	
Check /adjust alignment					4.00	
Install seat belts	325.00				8.00	2.00
Change engine oil & filter	71.50				0.50	
Fuel injection upgrade Includes new intake manifold	6760.00		2.00		50.00	2.00
Replace air cleaner & filter (aftermarket performance)	52.00					
Paint touch up doors & rocker panels Wet sand Rub out & polish	260.00	24.00	8.00			
Complete detail interior & exterior, including engine bay	650.00					
Fuel	54.60					
Total Labor Hours		24.00	10.00	0.00	142.00	8.50
Labor Rate per Hour		\$ 95.00	\$ 95.00	\$ 95.00	\$ 95.00	\$ 95.00
Totals	\$ 11,323.65	\$ 2,280.00	\$ 950.00	\$ -	\$ 13,490.00	\$ 807.50
\$ -						
\$ -						
\$ -						
Total Outsourced Work	\$ -					

Remittance Address: 24331 Brest Road Taylor, MI 48180
 Ph: (734) 947-7002 Fax: (734) 947-2551
 Email: vendor@mcshtrod.com
 Motor Vehicle Registration No: F165288

Materials subtotal	\$	11,323.65
Labor subtotal	\$	17,527.50
Shop supplies	\$	50.00

Description	Parts/ Materials	Labor Hours				
		Body	Paint	Trim	Mech	Fab
All Repairs Properly Performed P.A. 300						
	Outsourced work				\$	-
	Shipping fees				\$	60.00
	Transport vehicle				\$	-
X _____	SUBTOTAL				\$	28,961.15
Mechanic's Name & MI Certification No. Scott Dronsella #M202111 Rick Carpenter #M273182	MI sales tax @ 6%				\$	686.02
	TOTAL JOB COST				\$	29,647.17
	<i>Payments/Credits Received</i>				\$	-
					\$	-
	BALANCE DUE				\$	29,647.17

