



18 Railroad Avenue
Valley Stream, NY 11580
(516)398-2016

Customer's Information
Professional Auto Exchange
1448 Ford Road
Bensalem, PA 19020
(215)633-0775
mike@pro-auto.com

Qty	Part #	Description	Amount	Vehicle Information	
				Date	Year / Model / Make
12	15w50	Motor Oil	153.00	9/10/16	Lamborghini Countach
3	Prestone	Antifreeze	63.00		
2	ATE	Type 200 Brake Fluid	44.00		VIN #
14	Agip	85w90 Gear Oil	343.00		ZA9CA05A6KLA12627
8	Paint	Wrinkle & Chassis	144.00		Odometer
1	12'	Cloth Heater Hose	216.00		10053 km
86	Zinc-OEM	Bolt, Nut, Washer	230.00		Motor #
2	OEM	Fuel Filter	96.00		L507V471-1840
1	OEM	Fuel Control Relay	129.19	Accessories	
48	OEM	Sealing Ring	120.00	Refinish all yellow zinc	1,650.00
1	OEM	Fuel Pump	580.00	Front Brake Hoses	120.00
2	OEM	Fuel Accumulator	820.00	Clutch Hose	70.00
12	OEM	Spark Plug	336.00	Spark Module Update	1,800.00
2	OEM	Air Filter	160.00	Labor	
1	OEM	Valve Cover Set	360.00	Labor to perform engine restoration.	
1	OEM	Engine Oring Seal Kit	168.00	Replace clutch assembly, gaskets & seals.	
1	OEM	Sealant	78.00	Refinish all engine components.	
4	OEM	Motor Mount	400.00	Replace hoses, clamps, hardware.	
2	OEM	Transmission Mount	200.00	Engine mounts, trans mounts.	
1	OEM	Fuel Hose & clamps	128.00	All filters, fluids, spark plugs.	
1	Kevlar	Clutch Assembly	6,000.00		

Notes:

Parts:	10,768.19
Labor:	34,650.00
Accessories:	3,640.00
Subtotal:	49,058.19
Sales Tax 8.625%	Resale Certificate

Total: \$49,058.19

***Please make checks payable to: Giannetti Performance Inc

Thank you for your business!!

Bentley Certified Pre-Owned Technical Assessment



Vehicle Make: LAMBORGHINI
 Model: COUNTACH
 Licence/Plate:
 Miles/Kilometres: 10062 KM
 Retail Date:
 Vehicle Identification Number: ZA9CA05A6KLA12627
 Bentley Certified Technician: DAVE KEINER
 Assessment Date: May 1, 2017

Operation and Condition Check

Final Preparation

Check For Leaks And Leaks

1. Engine Oil
2. Transmission Oil
3. Power Steering Fluid
4. Brake Fluid
5. Hydraulic Oil
6. Engine Coolant (inc specific gravity)
7. Washer Reservoir
8. Fuel System Leaks
9. Final Drive Oil

Function Test

10. Check for Outstanding Recalls/Service Campaigns and Software Downloads
11. Parking Brake Operation
12. Bonnet/Boot Release and Safety Catch
13. Operation of Doors, Boot, Glove Box etc
14. Fuel Filler Release
15. Battery Condition
16. Heated Rear Screen and Heated Door Mirrors
17. All Lamps/LED's
18. Self Levelling and Adaptive Headlamp System
19. Headlamp Alignment
20. Direction Indicators
21. Screen Wipers, Washers and Wiper Delay
22. Headlamp Washers/Wipers
23. All Switches
24. Instrument Illumination (Including Dimmer)
25. All Facia Gauges and Driver Information Panel
26. Panel Warning Lights
27. Door and Interior Mirrors
28. Electric Window Operation
29. Horn
30. Seat Heaters, Motors, Mechanisms and Adjusters
31. Alarm/Immobiliser/Security Systems
32. In Car Entertainment
33. Cigar Lighter
34. Central Locking System
35. Fuseboard, Illumination and Spares
36. Hood Operation/Detachable Roof Mechanism*

* Model Specific

37. Ignition/Starters
38. Suspension and Shock Absorbers
39. Engine and Suspension Mountings
40. Steering and Suspension Joints
41. Wheel Bearings for Wear and Adjustment
42. Rubber Boots and Gaiters
43. Propeller Shafts/Drive Shafts - Condition/Tightness
44. All Drive Belts - Condition/Tightness
45. Brake Pipes and Hoses - Condition and Security
46. Brake Pads for Wear/Serviceability
47. Underbody and Exhaust (incl Catalytic Converter) Damage/Corrosion
48. Check Operation of Exhaust Solenoid Valve
49. Clear Body Drains
50. From Below - Check Security of all Fittings
51. Seat Belts - Check for Fraying and Security
52. Wheels (incl Spare) for Condition, Appearance and Damage
53. Tyres (incl Spare) condition and Min 3mm Tread Depth
54. Tyre Pressure (incl Spare)
55. Tyre Pressure Monitoring and Warning Systems
56. Check Visible Wiring Condition

Road Test and Operational Checks

57. Engine Function
58. Turbo/Supercharger Performance
59. Gear Selection 'P' and 'N' Position and Manual Overrides (e.g. Paddleshifts)
60. Auto Gear Change Including Kickdown
61. Final Drive
62. Speed/Cruise Control Systems
63. Vehicle Performance/Driveability (Including Wind Noise)
64. Shock Absorbers/Suspension Systems
65. Steering
66. Foot/Handbrake Efficiency
67. Air Conditioning/Climate Control/Ventilation Systems
68. All Adjustments and Switches
69. Sat Nav/ Route Finding Equipment
70. Check all Warning Lights

After Road Test

71. Check for Visible Leaks
72. Glass for Chips, Cracks, Delaminating and Correct Legal Tint
73. Bodywork Commensurate with Age/Miles (no dents/scratches)
74. Carpets Commensurate with Age/Miles (Appearance and Security)
75. Upholstery and Headlining, Appearance and Security
76. Veneers and Trim, Appearance and Security

77. Check Service History and Update if Necessary
78. Check the Operation of the Spare Key Fob
79. Compliance with Statutory Inspection Requirements

Comments

Tires Flat Spotted - tread at 5mm

Brake Hydraulic system (Brake pedal very low to the floor)

Clutch Pedal releases high - clutch feels ok

Both front fog lamps inop

Left front and left rear marker lights inop

DEALER STAMP

Signed on
 Behalf of Dealer



Customer's Information
Professional Auto Exchange 1448 Ford Road Bensalem, PA 19020 (215)633-0775 mike@pro-auto.com

Work Repair	Vehicle Information	
<ul style="list-style-type: none"> - Oil / Filter Service - Checked brake hydraulic system and clutch pedal high per Lamborghini dealer. - Brake Bleeding <p>**Vehicle meets all requirements and passes shop inspection.</p>	Date	Year / Model / Make
	5/25/18	Lamborghini Countach
	VIN #	
	ZA9CA05A6KLA12627	
	Odometer	
	10,065	
	Accessories	
	Amount	
	Miscellaneous	
	Notes:	

Parts:	***
Labor:	***
Accessories:	***
Subtotal:	930.00
Sales Tax 8.625%	Resale Certificate
Total:	\$930.00

PAID
5/28/18
PAID IN FULL

***Please make checks payable to: Giannetti Performance Inc
Thank you for your business!!



Customer's Information
 Professional Auto Exchange
 1448 Ford Road
 Bensalem, PA 19020
 (215)633-0775
 mike@pro-auto.com

Work Repair	Vehicle Information	
- Oil / Filter Service - Brake Fluid System Flush <div style="text-align: center;"> PAID <i>PAID IN FULL</i> <i>JK 4/14/17</i> </div>	Date	Year / Model / Make
	4/14/17	Lamborghini Countach
	VIN #	
	ZA9CA05A6KLA12627	
	Odometer	
	10,059	
	Accessories	
	Amount	
	Miscellaneous	
	Notes:	

Parts:	***
Labor:	***
Accessories:	***
Subtotal:	650.00
Sales Tax 8.625%	Resale Certificate

Total: \$650.00

***Please make checks payable to: Giannetti Performance Inc
 Thank you for your business!!



Customer's Information
 Professional Auto Exchange
 1448 Ford Road
 Bensalem, PA 19020
 (215)633-0775
 mike@pro-auto.com

Work Repair	Vehicle Information		
**Oil / Filter Service	Date	Year / Model / Make	
	4/15/16	Lamborghini Countach	
		VIN #	
		ZA9CA05A6KLA12627	
		Odometer	
		10,055	
		Accessories	Amount
	Miscellaneous		
Notes:			

PAID SK.
 4/16/16.
 PAID IN FULL.

Parts:	***
Labor:	***
Accessories:	***
Subtotal:	450.00
Sales Tax 8.625%	Resale Certificate
Total:	\$450.00

***Please make checks payable to: Giannetti Performance Inc
 Thank you for your business!!