

CUSTOMER #: 1405008

293007

**BENTLEY**

INVOICE

BENTLEY ATLANTA
 10995 Westside Parkway
 Alpharetta, GA 30009
 (770) 284-3519

PAGE 2

5680

SERVICE ADVISOR: 995857 SUZANNE SMITH

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	07	BENTLEY Continental	SCBCR73W57C048973		32495/32502	T7581	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
06JUN07 DD		06JUN2010	17:00 03JUN25		0.00	CASH	11JUN25
R.O. OPENED		READY	OPTIONS: DLR:407A17				
16:52 03JUN25		11:02 11JUN25					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	N10528301	BATTERY	KEY REMOTE		22.40	22.40	22.40
1	07C133238F	SEAL			31.75	31.75	31.75
12	101905600B	SPARK PLUG			43.65	43.65	523.80
1	G052565A1	SILICONE PASTE			52.16	62.16	62.16
PARTS: 1974.85 LABOR: 2136.00 OTHER: 0.00				TOTAL LINE C:		4110.85	

 D diag car
 CAUSE: diag

 MISC diag time to check over declined control
 arms alignment hood struts

995835 CPCB 1.00 260.00 260.00

 PARTS: 0.00 LABOR: 260.00 OTHER: 0.00 TOTAL LINE D: 260.00
 check over car call hesco

E** replace main battery

CAUSE: main battery cells are worn out.

MISC replace main battery as needed

995835 CPCB 1.00 260.00 260.00

 1 000915089BE BATTERY, FILLED AND
 CHARGED 499.99 494.98 494.98

1 BDB Battery Disposal Bentley 1.00 1.00 1.00

 PARTS: 494.98 LABOR: 260.00 OTHER: 1.00 TOTAL LINE E: 755.98
 replace main battery

ESTIMATE: 0.00 04JUN25 16:45 SA: 995857

CONTACT:

CUSTOMER PAY SHOP SUPPLIES FOR REPAIR ORDER

39.43

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

***SHOP SUPPLY COSTS:** We have added a charge equal to 10% of the total cost of labor and parts, not to exceed \$39.43, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
PARTS ADJUST	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

DATE CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

 REMIT TO: 4365 River Green Parkway, Suite 100
 Duluth, GA 30096

CUSTOMER #: 1405008

293007



BENTLEY

INVOICE

BENTLEY ATLANTA

 10995 Westside Parkway
 Alpharetta, GA 30009
 (770) 284-3519

PAGE 1

5680

SERVICE ADVISOR: 995857 SUZANNE SMITH

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
	07	BENTLEY Continental		SCBCR73W57C048973		32495/32502		T7581
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
06JUN07 DD		06JUN2010	17:00 03JUN25		0.00	CASH	11JUN25	
R.O. OPENED		READY	OPTIONS: DLR:407A17					

16:52 03JUN25 11:02 11JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CHECK ENGINE LIGHT

MISC REPLACE VACUUM LINES AND MASS AIR FLOW

SENSOR BANK 1

995835 CPCB 13.00

3536.00

3536.00

1 07D906461 AIR MASS METER

472.48

472.48

472.48

1 N90921901 O-RING

45.32

45.32

45.32

1 3W1612041S VACUUM PIPE

512.98

512.98

512.98

1 3W1612041R VACUUM PIPE

1137.49

1137.49

1137.49

3 3W0612391M CLAMP

15.08

15.08

45.24

2 N10197601 EAR CRIMP HOSE CLAMP

11.32

11.32

22.64

5 N10201801 CLAMP

13.06

13.06

65.30

1 JNV862564F CENTR. HYDRAULIC OIL

32.33

82.33

82.33

PARTS: 2383.78 LABOR: 3536.00 OTHER: 0.00 TOTAL LINE A:

5919.78

B AC NOT COOL

MISC EVACUATE AND CHARGE AC ADD DYE

995835 CPCB 1.50

390.75

390.75

PARTS: 0.00 LABOR: 390.75 OTHER: 0.00 TOTAL LINE B:

390.75

C CHECK FOR NEEDED SERVICE

 MISC completed tune up service as needed lube oil
 & filter spark plugs brake flush scan air
 filters pollen filters battery remotes

995835 CPCB 8.00

2136.00

2136.00

1 3W0129620B FILTER ELEMENT

230.98

230.98

230.98

1 3W0129620C FILTER ELEMENT

230.98

230.98

230.98

14 G0529302B ENGINE OIL

21.99

18.29

256.06

1 07C115562E FILTER ELEMENT WITH GASKET

41.94

41.94

41.94

1 N90813202 SEAL BOLT WITH SEALING RING

12.34

12.34

12.34

2 3W1955425D WIPER BLADE

121.42

121.42

242.84

1 3D1819619A DUST AND POLLEN FILTER

107.98

107.98

107.98

1 3D1819620B DUST AND POLLEN FILTER

107.98

107.98

107.98

1 000096311A CLEANER

39.38

39.38

39.38

1 B0001244554 BRAKE FLUID

64.26

64.26

64.26

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

***SHOP SUPPLY COSTS:** We have added a charge equal to 10% of the total cost of labor and parts, not to exceed \$39.43, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
PARTS ADJUST	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

DATE CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

 REMIT TO: 4365 River Green Parkway, Suite 100
 Duluth, GA 30096

CUSTOMER #: 1405008

293007

**BENTLEY**

INVOICE

BENTLEY ATLANTA
 10995 Westside Parkway
 Alpharetta, GA 30009
 (770) 284-3519


PAGE 3

1680

SERVICE ADVISOR: 995857 SUZANNE SMITH

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	07	BENTLEY Continental	SCBCR73W57C048973		32495/32502	T7581	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
06JUN07 DD		06JUN2010	17:00 03JUN25		0.00	CASH	11JUN25
R.O. OPENED		READY	OPTIONS: DLR:407A17				
16:52 03JUN25		11:02 11JUN25					
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

You will receive an email invitation from your Manufacturer to take a survey, evaluating your experience. We encourage you to take the survey, as it will help us to improve and serve you better on future visits. Thank you very much for your business. Your Nalley Service Team.

**BENTLEY**

STATE

376.23

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

*SHOP SUPPLY COSTS: We have added a charge equal to 10% of the total cost of labor and parts, not to exceed \$39.43, to the Repair Order for shop supplies used in connection with this repair.

**ALL PARTS ARE NEW
UNLESS OTHERWISE
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	6582.75
PARTS AMOUNT	4853.61
PARTS ADJUST	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES *	40.43
TOTAL CHARGES	11476.79
LESS INSURANCE	0.00
SALES TAX	376.23
PLEASE PAY THIS AMOUNT	11853.02

DATE CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

 REMIT TO: 4365 River Green Parkway, Suite 100
 Duluth, GA 30096