

CAMARO HI-PERFORMANCE INC.
Consultant, Appraisal and Authentication Services

032

Jerry MacNeish
3816 Collier Road
Randallstown, Maryland, 21133
Phone number 410-922-2927

CERTIFICATE OF AUTHENTICITY

Owners Name: Vinny Guarriello Address: 46 Summerfield Rd.

City: Belvidere State: N.J. Zip code: 07823

Vehicle Make: Chevrolet - Camaro Model: COPO Year: 1969

VIN Number: 124379N660826

Trim Plate Data: NO2# 353113, Build date 06A

Paint code 50-50, trim 711 Black std int. X44-D80

Drive Train Numbers:

Engine: N/A

Transmission: N/A

Rear Axle: N/A

Documentation: None

Paint Condition: primer - being restored

Interior Condition: restoration in progress

Engine Bay: restoration in progress

Under Cabbage: _____

Estimated Value and Comments: after close evaluation, this 1969 Camaro left the Norwood plant as a factory COPO 427 car. This can be documented by several items on the car: X-44-D-80 trim plate, tail pipe adapter plate, Disc brake master cylinder + brake booster, radiator, 3/8 single gas line tank unit, and no drilled holes for radio ground straps. The build date of the car (06A) indicates that this 1969 Camaro was built during the prime time of COPO production. It is my belief that this Camaro is an authentic Factory 427 car. If restored to new condition, this car will have an estimated value of at least \$120,000.00 or greater. To be determined when finished.

Jerry MacNeish

Jerry MacNeish: Appraiser

Technical Advisor, United States Camaro Club

Technical Advisor, International Camaro Club